

RIVERLEA VILLAGEWIDE STREET AND INFRASTRUCTURE IMPROVEMENTS - PUNCHLIST ROUND 2

updated 5.20.19

GENERAL

<u>Location</u>	<u>Details</u>	<u>Status</u>
Village wide	Remove the No Parking signs	
Riverglen at circle	Remove the port a john	
Village wide	Remove asphalt chunks and debris in the gutter pan	
Traffic circle	On north side there is a sprinkler hose and roots sticking up, needs cut back.	

72 Riverglen	Resident reports service box is too high, needs lowered	Not yet done
258 Southington	Owner claims additional damage to asphalt drive	Lots of alligator cracking on the old section, this is pretty consistent. There is a section on the left corner, maybe 1ft x 10" approx, was replaced as part of driveway repair. Contractor has met obligations.
31 Southington	Per Chief Bailot, 3 feet clearance needed between hydrant and	Not yet done
5835 Olentangy	Water valve is 12" high in the yard.	Has probably been lowered already. Grass was high but I couldn't find it. Will check when resident mows grass.